

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:					
OGM	Pete Hess				
Company	Scott Dimick				
Company	Dave Shaver				

Inspection Report

Permit Number:	C0070033				
Inspection Type:	COMPLETE				
Inspection Date:	Monday, October 04, 2010				
Start Date/Time:	10/4/2010				
End Date/Time:	10/4/2010				
Last Inspection:	Monday, September 20, 2010				

Inspector: Pete Hess,

Weather: Some cumulus clouds; windy. Storms forecast.

InspectionID Report Number: 2515

Accepted by: jhelfric 10/6/2010

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: WILDCAT LOADOUT

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

100.00	100.00 Total Permitted			
78.45	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

Types of Operations

Underground

✓ Federal

☐ State
☐ County

☐ Surface ✓ Loadout

☐ County

✓ Processing

Other

Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Leter Hess

Date

Monday, October 04, 2010

Pete Hess,

Inspector ID Number: 46

Permit Number: C0070033 Inspection Type: COMPLETE

Inspection Date: Monday, October 04, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers	✓			
3.	Topsoil	✓		~	
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	V		✓	
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		~	
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		V		
13.	Revegetation	✓		✓	
14.	Subsidence Control		V		
15.	Cessation of Operations	V		✓	
16.8	a Roads: Construction, Maintenance, Surfacing	V			
16.b	Po Roads: Drainage Controls	✓			
<u>17.</u>	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	~			
20.	Air Quality Permit	V			
21.	Bonding and Insurance	V			
22.	Other				

Permit Number: C0070033 Inspection Type: COMPLETE

Inspection Date: Monday, October 04, 2010

Page 3 of 3

3. Topsoil

The Permittee initiated the spreading of straw in the area north of Pond "A" and topsoil pile "A", and east of Primary Road PR-5. A crew of six men was hand spreading the straw. Mr. Scott Dimick then disced the straw into the soil, prior to hand broadcasting of the seed mix. An application rate of 19 pounds / 1000 pounds of straw mulch is to be implemented.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

All sediment ponds were observed as dry, although the County received some rain from thundershowers during the PM hours of October 3, 2010. All inlets and outlets were observed as capable of functioning as designed. The 3rd quarter impoundment inspections were conducted by Mr. Shaver on September 8, 2010. All ponds were noted as stable; no compliance issues were identified, either on 9/8 or during today's inspection.

4.d Hydrologic Balance: Water Monitoring

The Permittee notified the Division on October 4, 2010 that the Second Quarter of 2010 water monitoring information for the Wildcat permit area, as well as all of the other UtahAmerican permit areas was in the DOGM electronic data base pipeline ready for uploading.

4.e Hydrologic Balance: Effluent Limitations

None of the sites six UPDES outfalls were close to discharging; as noted elsewhere, all ponds were observed as dry. The current UPDES permit remains in effect through April 30, 2013.

7. Coal Mine Waste, Refuse Piles, Impoundments

The Wildcat waste rock pile inspection for third quarter was completed in September 2010. Mr. David Hibbs, P.E., certified and stamped the 3rd quarter report on September 20, 2010. All slopes were reported as stable. As observed this day, no water was being impounded on the pile. The evidence of combustion of the material was not evident.

9. Protection of Fish, Wildlife and Related Environmental Issues

No wildlife was observed during today's inspection.

13. Revegetation

The discing and seeding of the area where coal fines were recovered is relevant to the stabilization of this area until the topsoil can be recovered, post Pond "G" construction.

15. Cessation of Operations

The Wildcat Loadout is in temporary cessation status.